

**Test Report** Number: GZHH00531333

Applicant: FLASHBAY ELECTRONICS

BUILDING2, JIXUN INDUSTRIAL PARK, XINJIAO, DONG'AO VILLAGE, SHATIAN TOWN, HUIYANG DISTRICT, HUIZHOU CITY, GUANGDONG PROVINCE,

P. R. CHIŃA

Sample Description:

Thirteen (13) pieces of submitted sample said to be: Item Name **Travel Cups** Item No. Aroma (AM)

China

Country of Origin
Date Sample Received Mar 21, 2024 & Mar 26, 2024 & Apr 16, 2024

Testing Period Mar 21, 2024 ~ Apr 23, 2024

> Tested Sample GZHH00531333-01 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66



Date:

Apr 25, 2024

Tests conducted:

As requested by the applicant, refer to attached page(s) for details.

To be continued



Page 1 of 4

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China.

广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编: 510730)

Tel +8620 28209114 intertek.com.cn intertek.com





**Test Report** Number: GZHH00531333

Conclusion:

Tested sample Test Item Result Tested components of Applicant's requirement on Bisphenol -A Content Pass

submitted samples

Authorized by: For Intertek Testing Services Shenzhen Ltd. Guangzhou Branch, Hardlines

Victor T.J/Wang

Assistant General Manager

Tel +8620 28209114 intertek.com.cn

Page 2 of 4

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

510730)

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu

intertek.com 房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编:





**Test Report** Number: GZHH00531333

## **Tests Conducted**

## 1 **Bisphenol-A Content**

By solvent extraction and followed by Liquid Chromatographic / Tandem Mass Spectrometer (LC/MS/MS) analysis.

		Result (mg/kg)	Reporting	Limit
Test item	CAS No	Tested component	<u>limit</u>	<u>Limit</u> (mg/kg)
		(1), (2), (3)	<u>(mg/kg)</u>	(IIIg/kg)
Bisphenol-A	80-05-7	ND	0.1	ND

ND = Not detected(less than reporting limit)

## **Tested Components:**

- (1) (2) (3) Semi-transparent white silicone (seal ring).
- Black plastic (lid).
- Black soft plastic (sealing stopper of lid).



Page 3 of 4





Test Report Number: GZHH00531333

**Tests Conducted** 



Remark: The products in the reference photo are not tested in this report. It's declared by the applicant that they are the same series of products with the particular tested sample, just included in the report for reference.

End of report

The statements of conformity reported have considered the decision rule agreed, namely that Intertek have taken account of measurement uncertainty as calculated by Intertek, and applied according to ILAC-G8/09:2019 (Non-binary acceptance based on guard band  $\mathbf{w} = \mathbf{U}$ ) except designation from the customer, regulation or test specification. This decision rule only applies to the numeric test results.

The sample(s) and sample information hereto are provided by the client who shall be solely responsible for the authenticity and integrity thereof. The results shown in this report relate only to the sample(s) tested. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. This report shall not be reproduced unless with prior written approval from Intertek Testing Services Shenzhen Limited, Guangzhou Branch. The testing data and result issued by this report are just for scientific research, teaching, internal quality control, product research and development etc. on reference only in the territory of the People's Republic of China.



Tel +8620 28209114

intertek.com.cn intertek.com

Page 4 of 4

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China.

1003

