

Number: GZHH00592235

Apr 30, 2025

Date:

Applicant:

FLASHBAY ELECTRONICS BUILDING2, JIXUN INDUSTRIAL PARK, XINJIAO, DONG'AO VILLAGE, SHATIAN TOWN, HUIYANG DISTRICT, HUIZHOU CITY, GUANGDONG PROVINCE, P. R. CHINA

Sample Description:

amp	le said to be :
	Gadgets
:	WingMate-WM
:	China
:	Apr 23, 2025
:	Apr 23, 2025 ~ Apr 29, 2025
	amp



Tests conducted:

As requested by the applicant, refer to attached page(s) for details.

To be continued



Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China.

广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编: 510730) Tel +8620 28209114 intertek.com.cn intertek.com





Number: GZHH00592235

Conclusion:		
Tested sample	Standard/Testing Item	<u>Result</u>
Tested component(s) of	Consent Judgment No. CGC-09-485784 for total Lead content	Pass
submitted sample(s)	based on the California Proposition 65	
	Consent Judgment No. CGC-09-485784 & RG16829723 on	Pass
	phthalate content based on the California Proposition 65	
	Consent Judgment No. RG-585401 on phthalate content	Pass
	based on the California Proposition 65	
***************************************	***************************************	*******

Authorized by: For Intertek Testing Services Shenzhen Ltd. Guangzhou Branch, Hardlines

AN

Victor T.J Wang General Manager

Should you have any query on this report, please click the link below: https://verifyindex.intertek.com.cn/home/index?id=hl_report_verify



Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China.

广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编: 510730) Tel +8620 28209114 intertek.com.cn intertek.com





Number: GZHH00592235

Tests Conducted

1 <u>Total Lead (Pb) Content</u>

With reference to CPSC-CH-E1002-08.3 and/or CPSC-CH-E1001.08.3 and/or CPSC-CH-E1003-09.1 and followed by Inductively Coupled Argon Plasma Spectrometry.

	Result (mg/kg)	Reporting	Limit
Element Tested Component		<u>Limit</u>	<u>(mg/kg)</u>
	<u>(1), (2+3+4)</u>	<u>(mg/kg)</u>	
Lead (Pb)	ND	10	100

The above limit was quoted from the Consent Judgment No. CGC-09-485784 settled by superior court of the State of California for the county of San Francisco, for Identification Products based on the California Proposition 65.

ND = Not detected (less than reporting limit)

Tested Component(s): See component list in the last section of this report

2 Phthalate Content

With reference to CPSC-CH-C1001-09.4 and followed by Gas Chromatographic-Mass Spectrometric (GC-MS) analysis..

Test item	CAS No.	Result (%) <u>Tested component</u> (1), (2+3+4)	Reporting Limit (%)	<u>Limit</u> <u>(%)</u>
Dibutyl phthalate (DBP)	84-74-2	ND	0.01	0.1
Di-(2-ethyl hexyl) phthalate (DEHP)	117-81-7	ND	0.01	0.1
Benzyl butyl phthalate (BBP)	85-68-7	ND	0.01	0.1
Di-iso-nonyl phthalate (DINP)	28553-12-0/ 68515-48-0	ND	0.01	0.1

The above limit was quoted from the Consent Judgment No. CGC-09-485784 & RG16829723 settled by superior court of the State of California for the county of San Francisco & Alameda, for Identification Products based on the California Proposition 65.

ND = Not detected (less than reporting limit)

Tested Component(s): See component list in the last section of this report



Tel +8620 28209114 intertek.com.cn intertek.com

Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China.

广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编: 510730)



Number: GZHH00592235

Tests Conducted

3 Phthalate Content

With reference to CPSC-CH-C1001-09.4 and followed by Gas Chromatographic-Mass Spectrometric (GC-MS) analysis..

Test item	CAS No.	<u>Result (%)</u> <u>Tested component</u> (1), (2+3+4)	Reporting Limit (%)	<u>Limit</u> <u>(%)</u>
Di-(2-ethyl hexyl) phthalate (DEHP)	117-81-7	ND	0.01	0.1
Di-iso-nonyl phthalate (DINP)	28553-12-0/ 68515-48-0	ND	0.01	

The above limit was quoted from the Consent Judgment No. RG-585401 settled by superior court of the State of California for the county of Alameda, for Card holders with vinyl/PVC covers based on the California Proposition 65.

ND = Not detected (less than reporting limit)

Tested Component(s): See component list in the last section of this report

Components list:

- (1) White coating on synthetic leather (pattern of cover).
- (2) Black synthetic leather with glue (cover).
- (3) Black elastic band (fastener).
- (4) Black woven with glue (back of body).



Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China.

广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编: 510730) Tel +8620 28209114 intertek.com.cn intertek.com



Tests Conducted

Number: GZHH00592235



Remark: The products in the reference photos are not tested in this report. It's declared by the applicant that they are the same series of products with the particular tested sample, just included in the report for reference.

End of report

The statements of conformity reported have considered the decision rule agreed, namely that Intertek have taken account of measurement uncertainty as calculated by Intertek, and applied according to ILAC-G8/09:2019 (Non-binary acceptance based on guard band w = U) except designation from the customer, regulation or test specification. This decision rule only applies to the numeric test results.

The sample(s) and sample information hereto are provided by the client who shall be solely responsible for the authenticity and integrity thereof. The results shown in this report relate only to the sample(s) tested. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. This report shall not be reproduced unless with prior written approval from Intertek Testing Services Shenzhen Limited, Guangzhou Branch.



Intertek Testing Services Shenzhen Limited, Guangzhou Branch 深圳天祥质量技术服务有限公司广州分公司 Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China \111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China.

广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房。广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室。(邮编: 510730) Tel +8620 28209114 intertek.com.cn intertek.com

